FIG.1

## PROVIDE POROUS SILICA MATRIX



## VITRIFY IN FLUORINE COMPOUND GAS ATMOSPHERE



## **REMOVE INGOT SURFACE**



## SHAPE



**HEAT TREAT , CUT , POLISH**